

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
1	BRS	L1	5924	(transmission near line\$1) and microstrip L1 and delay\$1	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2003/09 /11 17:14		
2	BRS	L2	128	(common near signal\$1) and 11	USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2003/09 /11 17:14		

10/16/04 784

208 4005